DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-015265 Address: 333 Burma Road **Date Inspected:** 02-Jul-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: Chen Xi. **CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** OBG

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Shailesh Wadkar was present during the times noted above for observations relative to the fabrication of the Self Anchored Suspension (SAS) Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island, in Shanghai, China. QA observed and/or found the following:

Bay 1: CB15.

This QA Inspector observed that no significant work was being performed on the above mentioned CB at the time when this QA was present.

Bay 8: CB17.

This QA Inspector observed that no significant work was being performed on the above mentioned CB at the time when this QA was present.

Outside Yard:

CB14:

This QA Inspector observed the following work in progress:

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

Repair welding of weld joint no: CB202C-014-003. Welding process was identified as Shielded Metal Arc Welding (SMAW). Welder is identified as 043661. ZPMC Quality Control (QC) is identified as Wang Liang. The welding variables recorded by QC appeared to comply with the Applicable WPS:

WPS-345-SMAW-4G(4F)-FCM-Repair (WRR No: B-WR-13787). Photo attached for reference.

Repair welding of weld joint no: FB204-044-070. Welding process was identified as SMAW. Welder is identified as 043661. ZPMC QC is identified as Wang Liang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-345-SMAW-2G(2F)-Repair-1 (WRR No: B-WR-13777 Rev-0).

Repair welding of weld joint no: FB205-044-035. Welding process was identified as SMAW. Welder is identified as 043661. ZPMC QC is identified as Wang Liang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-345-SMAW-1G(1F)-Repair-1 (WRR No: B-WR-13784 Rev-0).

Repair welding of weld joint no: FB205-043-035. Welding process was identified as SMAW. Welder is identified as 043661. ZPMC QC is identified as Wang Liang. The welding variables recorded by QC appeared to comply with the Applicable WPS: WPS-345-SMAW-4G(4F)-Repair-1 (WRR No: B-WR-13782 Rev-0). Photo attached for reference.


CB11:

This QA Inspector observed this CB been shifted to Trial Assembly. No other significant work was being performed on this CB at the time when this QA was present.

CB12, CB13 & CB16:

This QA Inspector observed that no significant work was being performed on the above mentioned CB's at the time when this QA was present.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.





WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang; phone: 15000422372., who represents the Office of Structural Materials for your project.

Inspected By:	Wadkar, Sailesh	Quality Assurance Inspector
Reviewed By:	Hall,Steven	QA Reviewer